

gal 0274

0036

NO. N 92-37-1-1

notice of violation

To the following Permittee or Operator:

Name Utah Fuel Co.

Mine Skylark Mine

☐ Surface

☒ Underground

☐ Other

County Carbon State UT

Telephone (801) 637-7925

Mailing Address P.O. Box 719, Helper UT 84526

State Permit No. ACT 10071005

Ownership Category

☐ State

☒ Federal

☐ Fee

☐ Mixed

Date of inspection 8/18 - 8/21, 19 92

Time of inspection 8/18 2:00

☐ a.m.

☒ p.m. to

8/21 3:00

☐ a.m.

☒ p.m.

Operator Name (other than Permittee)

Mailing Address

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** ☐ **is not** ☐ expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED RETURN RECEIPT:

P 074 978 439

Date of service/mailling 8/24/92

Time of service/mailling 3:15

☐ a.m.

☒ p.m.

Permittee/Operator representative

Title

Signature

PRISCILLA BURTON
 Division of Oil, Gas & Mining representative

INSPECTOR

Priscilla Burton
 Signature

#37
 Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 92-37-7-1

Violation No. 1 of 1

Nature of violation

Failure to provide maps & plans showing relevant surface configuration and slope; size and location of spoil and development waste areas.

(E)

Provisions of act, regulations or permit violated

R 645-301-521.124

R 645-301-521.150

Portion of operation to which notice applies

Railroad load out pad developed between the inlet and outlet of C/D 6 and bounded on the north & south by the disturbed area boundary.

Remedial action required (including any interim steps)

1. Provide an accurate, revised map of the rail road load out surface configuration and facilities.
2. provide information on slope as it pertains to drainage designs found in vol. 5.

Abatement time (including interim steps)

5pm, Friday, September 4, 1992